

| ITEM NO. | NAME | MATERIAL | QTY. |
|-------------|------------------------------------|------------------|------|
| 1 | Seat_Assembly_240610-0 | SEE SUB ASSEMBLY | 1 |
| 2 | Leg_Assembly_240610-0 | SEE SUB ASSEMBLY | 2 |
| 3 | SCHCSCREW 0.375-16x3.25x1.25-HX-S | STAILNESS STEEL | 2 |
| 4 | Screw_Seat_240610-0 | 6061 ALLOY | 4 |
| 5 | Foot_Rest_Assembly_240610-0 | SEE SUB ASSEMBLY | 1 |
| 6 | Backrest_Assembly_240610-0 | SEE SUB ASSEMBLY | 1 |
| 7 | SBHCSCREW 0.375-16x0.75-HX-S | STAINLESS STEEL | 4 |
| 8 | SCHCSCREW 0.375-16x2.75x1.25-HX-S | STAINLESS STEEL | 2 |
| 9 | FLATCKT 0.25-14-type IA-AB-1.813-S | STAINLESS STEEL | 12 |
| 10 | SET SCREW | STAINLESS STEEL | 2 |

IMPORTANT INFORMATION! MUST READ BEFORE ASSEMBLY - NEW PARTS ATTACHED TO BOX

New set screws have been provided with all Stryker LP100 leaning posts. These set screws are used for securing the back rest clamps to a desired position. Attached to the outside of the shipping box is a packet with two **pointed tip set screws** that are to be used instead of the <u>flat</u> tip set screws currently installed in the clamps. **Please discard the incorrect flat tip set screws**. Refer to part #10 in the schematic below which can be downloaded from strykerttops.com/installation-guides.

